

DMIE Procedure

EEE Parts Program

1. Title

Electronic, Electromechanical, Electromagnetic (EEE) Parts Program

2. Process

Parts Knowledge Management

3. Steps

Actor	Step	Action
Office 507	1	Identify the type of data or information required or desired. Use available sources for input of requests. The following is a representation of these sources: a. Technology Teams b. Customer Inputs c. Workshop Feedback d. Industry Interaction
Office 507	2	Determine the need for the information and suitability for future applications
Office 507	3	Develop plans a. Data collection plans b. Collaboration and Teaming Arrangements c. Data Collection Approaches d. Decisions for Performing the tasks internally or externally e. Sequester workforce and funds
Office 507	4	Generate Data a. Attend/Conduct Classes b. Generate Alerts c. Conduct Tests d. Perform Evaluations e. Perform Inspections

		<ul style="list-style-type: none"> f. Literature Search g. Participate in Conferences h. Publish Results
Office 507	5	Capture Data <ul style="list-style-type: none"> a. Develop and maintain Databases b. Conduct Training Classes c. Provide access to data files
Office 507	6	Data Processing and Analysis <ul style="list-style-type: none"> a. Perform Data Analysis b. Develop Conclusions and Recommendations
Office 507	7	Disseminate Information <ul style="list-style-type: none"> b. Conduct Classes c. Publish Results Externally and Internally d. Publish on Web site e. Participate in Conferences and Workshops f. Conduct Project Education Presentations
Office 507	8	Determine Suitability of Information <ul style="list-style-type: none"> a. Conduct Survey of Customers b. Determine suitability of data for publication c. Determine suitability of the dissemination process d. Determine suitability of the data collection process

4. Applicability

This procedure applies to all personnel developing electronic parts related information for the EEE Parts Program.

5. Tips (optional)

Additional information about electronic parts and parts engineering can be found at <http://parts.jpl.nasa.gov/>.

6. Source

Provide Electronic Parts Engineering
Design, Build, Assemble, Test
Design New Products Policy

7. Rationale

The procedure is intended to capture and maintain data and experiences developed through special studies or during the selection, acquisition and use of electronic parts. The special studies typically benefit current and future projects by providing the latest technical information regarding parts used in flight hardware. Data captured during the acquisition and build phases provide traceability, share solutions for problems and provide baseline information for future projects.

8. Consequences

Natural consequences:

- Lack of latest technical information on emerging technologies.
- Loss of parts experience from previous missions.
- Higher costs since research is not leveraged through partnering

9. Trigger/Result (optional)

TRIGGER: Identification of new technologies that have benefit potential for JPL missions.

RESULT: Determine the need for the information and suitability for future applications.

TRIGGER: Identification of electronic parts process data that could benefit future projects.

RESULT: Determine the need for the information and suitability for future applications.

10. Related Procedures (optional)

Parts Program Management
Develop Approach
Support Selection
Parts Acquisition
Post-Delivery Support
Parts Engineering Facility Management
Closed Loop Alert System

11. Frequently Asked Questions (optional)

[enter text here]

12. Change Description

This is a new procedure.

13. Notification (optional)

☒ **Visible Draft** or

☐ **Invisible Draft**

Reviewers:

ISO9001	
Arnett, J.	5050
Barela, P.	5060
Brace, R.	5150
Barath, F.	7000
Brejcha, A.	5000
Bunker, R.	3400
Casani, J.	5000
Cherniack, E.	5100
Clawson, J.	5050
Cooper, L.	3110
Cornford, S.	5050
Cunningham, G.E.	4900
Dickerson, M.	3440
Frerking, M.	7932
Frandsen, A.	3200
Fraschetti, G.	3870
Garrison, P.	3501
Gavin, T.	1400
Gavit, S.	7620
Geer, D	3440
Graf, J.	7830
Greanias, G.	5150
Gresham, L.	3440
Harris, W.	3800
Hoffman, A.	5050
Hovland, L	3870

Hunter, J.	7020
Johnson, D	3440
Jones, S.	5030
Kemski, R	5150
Kaki, S.	7700
Klein, J. Dr.	3440
Koch, J.	5050
Komarek, T.	3360
Kyriacou, C.	3360
Laeser, R.	1000
Langmaier, J.	3400
Lau, G.	3110
Lehman, D	7610
Livermore, T.	7240
Livesay, L.	7610
Marr, J	7240
McNamee, J.	4300
Menke, R.	5150
Miller, J.	5060
Muirhead, B	4100
Norris, D.	3870
Pace, G.	4500
Perret, J.	3360
Reh, K.	3440
Rose, J.	5170
Schlue, J.	5150
Simmons, L.	7500
Staehle, R.	7420
Stevens, C.	3870
Suggs, E.	4500
Suitor, J.	3100
Swenson, D.	7000
Woerner, D.	7410
Wright, L.W.	5040
Yamarone, C.	7700